

C-EB(XLR)

V-Mount to XLR Adaptor with Belt Loop



取扱説明書



このたびは、C-EB(XLR)をお買い求めいただきまして、ありがとうございます。C-EB(XLR)は、Vマウントバッテリー対応の小型変換アダプターです。ご使用に際しては、本書をよくお読みいただき、基本的な取扱方法や注意事項をご理解された上で、安全にお使いください。お読みになられた後は、いつでも見られるところに必ず保管してください。

安全にお使いいただくための注意

間違った使い方をした場合、火災、感電あるいは怪我や製品故障などの重大な原因となることもあります。事故を防ぐために、下記の項目を必ずお守りください。

⚠ 警告：死亡や重傷を負う危険が生じる可能性があります

- 機器の定格や使用条件を越えて使用しないでください。
- 端子間を金属類でショートさせないでください。また、金属製の物と一緒に持ち運んだり、保管しないでください。
- 水で濡らしたり、水中に投じないでください。
- 分解したり改造したりしないでください。
- 落下させたりハンマーで叩くなど、強い衝撃を与えないでください。
- 重い物を載せたり、圧力を掛けしないでください。
- ケーブルを傷つけないでください。
- ケーブル接続の際はケーブルを強く引っ張らないでください。
- 損傷が著しい場合は使用しないでください。

⚠ 注意：けがや物品損害が生じることがあります


- 必ず弊社指定の使用条件を守ってください。
- 高温環境下では使用しないでください。
- 水にぬれた場所や湿度の高い場所で保管しないでください。
- ご使用中に異臭や液漏れ・変色・変形などがあった場合は、ただちに使用を止めてください。
- バッテリーを接続したままの状態では移動や運搬は行わないでください。
- 使用後はバッテリーを取り外してください。
- ご使用される機器に適正な出力を供給するため、用途にあったケーブルをご使用ください。また、ご使用される機器の入力電圧をご確認の上、接続してください。

特 徴

- Vマウントバッテリーの出力をスルーアウトで4ピンXLRプラグに変化するアダプターです。
- ベルトループ付き。

仕 様


- 適応バッテリー：IDX製 Vマウント リチウムイオンバッテリー
- 出力プラグ：XLR 4 Pin (メス) / NC4FXX-B (NEUTRIK)
- 出力電圧：バッテリー電圧
- 使用温度範囲：-20℃～40℃ (推奨 10℃～40℃)
- 使用湿度範囲：20%～90% RH
- 最大定格：10 A
- 外形寸法：60(W)×106(H)×30(D) mm (突起部除く本体ケースのみ)
72(W)×106(H)×36(D) mm (ベルトループを含めた最大外形 / ケーブル除く)
出力ケーブル長さ 約 210mm (プラグ含まず)
- 重量：約 280 g



PIN	出 力
1	(-)
2	NC
3	NC
4	(+)

各部名称

- ① アダプター本体
- ② バッテリー リリースボタン
- ③ Vマウント
- ④ バッテリー入力端子
- ⑤ 出力プラグ
- ⑥ 出力ケーブル
- ⑦ ベルトループ



C-EB(XLR)

V-Mount to XLR Adaptor with Belt Loop



Instruction Manual



Thank you for purchasing the C-EB(XLR). C-EB(XLR) is a small conversion adaptor for IDX V-Mount battery. please read this manual carefully and understand the basic handling methods and precautions before using the product safely. After reading it, be sure to keep it in a place where you can see it at any time.

⚠ WARNING

May cause sudden serious injury and death

- Do not use the product beyond the rated or operating conditions of the device.
- Do not carry or store with metal equipment.
- Do not immerse in water.
- Do not attempt to open the outer casing or break apart.
- Do not subject the unit to extreme physical impact or pressure.
- Do not short the contact pins with any metal object.
- Do not attempt to use if damaged.
- Do not place heavy objects or apply pressure.
- Do not damage the cable.
- When connecting the cable, do not pull the cable strongly.

⚠ CAUTION

May cause sudden serious injury and death


- The unit should be used under the conditions listed in this manual.
- Do not expose the unit to extremely high temperatures.
- Keep the unit away from fluid or high humidity environment.
- Remove it from the device and stop using it immediately If an odour, leakage, discoloration or deformation is noticed. Do not carry the adaptor while the battery is attached.
- Remove the battery after use.
- Check the input voltage of the device to be used before connecting.

Features

- Output unregulated voltage from attached battery to XLR plug
- Equipped with belt loop

Specifications


- Recommended batteries : IDX V-mount battery
- Output plug : XLR 4pin / NC4FXX-B (NEUTRIK)
- Output voltage : DC Unregulated
- Ambient temperature : -4 ~ 113°F (-20 ~ 45°C) (50 ~ 104°F (10 ~ 40°C) recommended)
- Ambient humidity : 20 % ~ 90 % RH
- Maximum discharge current : 10 A
- Dimensions : approx. 60 (W) × 106 (H) × 30 (D) mm
approx. 2.36 (W) × 4.17 (H) × 1.18 (D) inches
*Warning. Do not use these dimensions for reference.
approx. 72 (W) × 106 (H) × 36 (D) mm
approx. 2.59 (W) × 4.17 (H) × 1.41 (D) inches
*Warning. Maximum external dimensions including a belt loop
Cable length approx. 210mm / 8.26inches
- Weight : approx. 280g / 0.62 lbs



PIN	Output
1	(-)
2	NC
3	NC
4	(+)

Parts Description

- ① Adaptor
- ② Battery release button
- ③ V-mount
- ④ Battery connector
- ⑤ Out put plug
- ⑥ Out put cable
- ⑦ Belt loop



Design and specifications are subject to change without notice.

